

Description: Please provide any and all documents regarding work orders for: sidewalk inspections, sidewalk maintenance, sidewalk repair, tree inspection, tree removal, public work projects, sidewalk projects. The request is made for the area located along the eastern sidewalk of Venetian Drive from March Lane to Passero Way. Date range is 2009 through present.

Sidewalk Inspections and Temporary Sidewalk Repair

Date	Work Order No.	Address
6/3/2015	10860	1834 Venetian Dr
6/11/2015	11133	Venetian Dr & Mosaic Wy
1/29/2016	27611	Venetian Dr & Griffin Pt
3/22/2016	31299	1834 Venetian Dr
9/25/2017	84869	2436 Venetian Dr
9/27/2018	98236	1546 St Marks Pz
7/9/2019	143664	1934 Venetian Dr
8/23/2019	149580, 149951	2436 Venetian Dr

Sidewalk Repair Projects

Year	Project No.	Project Name	Address	Sidewalk Replaced (SF)	Vertical Curb Replaced (LF)
January 2018	PW1531	Sidewalk - Tree Repairs Project Phase 1	2022 Venetian Dr	330	
January 2018	PW1531	Sidewalk - Tree Repairs Project Phase 1	5355 Passero Wy	170	
February 2020	PW1815	Sidewalk, Curb, and Gutter Repairs Program FY18-19 SB1	2034 Venetian Dr	347	
October 2021	WD21004	Sidewalk, Curb, and Gutter Repairs Program FY20-21 SB1	1934 Venetian Dr	520	104
December 2022	WD22004	Sidewalk, Curb, and Gutter Repairs Program FY21-22 SB1	Venetian Dr & Mosaic Wy	750	

Tree and Stump Removals

Date	Work Order No.	Address	Project No.	Project Name	Tree Removals (EA)
8/25/2015	15913	5355 Passero Wy	PW1531	Sidewalk - Tree Repairs Project Phase 1	1
9/10/2015	16776, 16875	1934 Venetian Dr	NA - City Tree Crew	NA	1
11/3/2018	119180	2034 Venetian Dr	PW1815	Tree Removal and Stump Grind	2

Part 1							
Date	Work Order #	Work Order Type	Address	Project No.	Project Name	Tree Removals (EA)	Notes
9/20/2018	119359	Inspection	1702 Venetian Dr	PW 1815	Sidewalk, Curb, and Gutter Repair Program FY 2018-19 SB1		
8/20/2015	15813	Tree Removal Contractor (Sidewalk Repairs)	5355 Passero Wy	PW 9969	2015 Sidewalk Project		1
12/16/2019	159691	Inspection	1702 Venetian Dr				
5/27/2020	172425	Inspection	5340 Passero Wy				
5/27/2020	172436	Tree Removal COS (Non-Emergency)	5340 Passero Wy				1
3/11/2021	204030	Stump Removal	5340 Passero Wy				
3/7/2016	30898	Inspection	5340 Passero Wy				
3/10/2016	31446	Re-Inspection	5340 Passero Wy				
2/6/2017	61540	Inspection	5356 Passero Wy				
Part 2							
Date	Work Order #	Work Order Type	Address	Project No.	Project Name	Tree Removals (EA)	Notes
6/11/2015	11392	Concrete - Curb & Gutter	VENETIAN DR & MOSAIC WY				
1/16/2019	129520	Inspection	1835 Venetian Dr				
9/8/2015	16598	Inspection	1934 Venetian Dr				
8/17/2020	185336	Inspection	1913 Venetian Dr				
8/9/2021	217841	Inspection	2098 Venetian Dr				
8/9/2021	217931	Tree Removal COS (Non-Emergency)	2098 Venetian Dr		Tree Removal List		1
12/10/2021	229174	Stump Removal	2098 Venetian Dr	WE 22052	Citywide Tree Maintenance Project		
5/3/2016	36098	Inspection	2022 Venetian Dr	PW 9969	2015 Sidewalk Project		
Part 3							
Date	Work Order #	Work Order Type	Address	Project No.	Project Name	Tree Removals (EA)	Notes
9/20/2018	119235	Inspection	2314 Venetian Dr	PW 1815	Sidewalk, Curb, and Gutter Repair Program FY 2018-19 SB1		
8/6/2019	147991	Inspection	2301 Venetian Dr				
8/6/2019	147996	Tree Removal Contractor (Non-Emergency)	2301 Venetian Dr	PW 2124	Tree/Stump Removal		
8/6/2019	147997	Tree Removal COS (Non-Emergency)	2301 Venetian Dr		Tree Removal List		1
8/6/2019	147998	Stump Removal	2301 Venetian Dr	PW 2124	Tree/Stump Removal		
5/6/2020	170801	Paint - Curb	E March Lane & Holman Rd				Should not be included
9/30/2020	188948	Inspection	2323 Venetian Dr				
2/2/2021	200067	Tree Removal COS (Non-Emergency)	2301 Venetian Dr				1
8/9/2016	44766	Stump Removal	2301 Venetian Dr	PW 2124	Tree/Stump Removal		1

Work Order 119359
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB	Date: 09/20/2018
Requested By: FUSON, BOB	Supervisor: MACHADO, VICTOR
Projected Start: 9/20/2018 8:16:53AM	Submit to Date: 09/20/2018
Opened By: FUSON, BOB	Date: 07/31/2019
Closed By: FUSON, BOB	Projected Finish: 09/25/2018
Actual Start:	Actual Finish: 11/03/2018
Project Name: PW1815 Sidewalk, Curb, and Gutter Repair Program FY 2018-19 SB1	

<u>DATE</u>	<u>COMMENTS</u>
9/20/2018 8:16:53AM	From Requestt54764: Code: TR20 Descriptton: Inspectton Request(Sidewalks) Dettails Inspectt 3ttrees Commentts
11/3/2018 10:39:34AM	Recommend removing ttthree ttrees as partt ofi sidewalk repair/replacementt projectt PW1815.
1/5/2021 9:19:47AM	Trees were removed from locatton per recommendatton and associattted with projectt PW2104.
1/11/2021 9:12:42AM	ArcMap updatted.

Location Information

WO Address: 1702 VENETIAN DR
Location:

Instructions:

Completed By: FUSON, BOB

Date: 11/03/2018

Work Order 119359
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Map Image Unavailable.jpeg

Work Order 15813
Tree Removal Contractor (Sidewalk Repairs)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB
Requested By: FUSON, BOB
Projected Start: 8/20/2015 1:49:18PM
Opened By: FUSON, BOB
Closed By: FUSON, BOB
Actual Start:
Project Name: PW9969 2015 Sidewalk Project

Date: 08/20/2015
Supervisor: FUSON, BOB
Submit to Date: 08/20/2015
Date: 09/05/2015
Projected Finish: 08/25/2015
Actual Finish: 09/05/2015

Completed By: FUSON, BOB

Date: 09/05/2015

Work Order 15813
Tree Removal Contractor (Sidewalk Repairs)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

DATE

COMMENTS

1/1/1970 12:00:00AM

From Request5863:

Code: TR20

Description: Inspecton Request(Sidewalks)

Details (1) - 16" tto20" dbh

Comments

By FUSON, BOB: 9/5/2015 9:00:14 AM

Recommend removing one tree as part of tthe sidewalk repair projectt

All thtree trees here should be removed

7/26/2018 2:53:33PM

One tree was removed as part of Projectt PW1531.

7/26/2018 3:23:38PM

ArcMap updatedd.

Location Information

WO Address: 5355 PASSERO WY

Location: (1) - possible tree removal & stump

Instructions:

Map Image Unavailable.jpeg

Work Order 159691
Inspection

Cityworks

Status : CLOSED

Completed By: THOMASON, JUSTIN W

Date: 12/16/2019

Work Order 159691
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 12/16/2019 7:19:42AM
Opened By: THOMASON, JUSTIN W
Closed By: THOMASON, JUSTIN W
Actual Start:
Project Name:

Date: 12/16/2019
Supervisor: WONG, JAMES K
Submit to Date: 12/16/2019
Date: 12/16/2019
Projected Finish: 12/21/2019
Actual Finish: 12/16/2019

DATE
12/16/2019 7:19:42AM

COMMENTS
From Request#74806:
Code: TR008
Description: Misc Tree issue
Details AskStockton Request#4845376 - Three (3) trees in front of 1702 Venetian Drive are dangerous. The roots are damaging the sidewalksThe trees produce golf ball sized ballsThe damaged sidewalks and the balls are dangerous trip hazardsThe roots are intruding into the yard of the home and are getting close to the cement slab soon they will grow into and crack the slab. Now is a good time to remove the trees while the leaves are goneWould the City please remove the trees

12/16/2019 7:57:22AM

Attachment
Comments
The trees here are in satisfactory conditionSidewalk is uneven and displaced do to tree roots
Creatng SR for Sidewalk inspectorsDoor hangar left.

Location Information

WO Address: 1702 Venetian Dr
Location: Front

Instructions:

Completed By: THOMASON, JUSTIN W

Date: 12/16/2019

Work Order 159691
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Map Image Unavailable.jpeg

Work Order 172425
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: DOSIERSR, CHRIS A

Initiated By: DOSIERSR, CHRIS A
Requested By: DOSIERSR, CHRIS A
Projected Start: 5/27/2020 5:43:57AM
Opened By: DOSIERSR, CHRIS A
Closed By: DOSIERSR, CHRIS A
Actual Start: 05/27/2020
Project Name:

Date: 05/27/2020
Supervisor: WONG, JAMES K
Submit to Date: 05/27/2020
Date: 05/27/2020
Projected Finish: 06/01/2020
Actual Finish: 05/27/2020

Completed By: DOSIERSR, CHRIS A

Date: 05/27/2020

Priority:

3

Category: TREES

Submit To: DOSIERSR, CHRIS A

DATE

5/27/2020 5:43:57AM

COMMENTS

From Request80883:
Code: TR21
Description: Inspecton Request(Citizen)
Details
Comments inspecton tto see ifi ttree can be removed

5/27/2020 7:31:26AM Tree is in decline putt on rem

5/27/2020 7:32:08AM Tree is in decline putt on removal listt.

Location Information

WO Address: 5340 PASSERO WY

Location: Front

Instructions:

Map Image Unavailable.jpeg

Work Order 172436
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: CAMPOS, JOEL A

Initiated By: DOSIERSR, CHRIS A **Date:** 05/27/2020
Requested By: DOSIERSR, CHRIS A **Supervisor:** WONG, JAMES K
Projected Start: 5/27/2020 7:34:50AM **Submit to Date:** 05/27/2020
Opened By: CAMPOS, JOEL A **Date:** 03/10/2021
Closed By: THOMASON, JUSTIN W **Projected Finish:** 05/29/2020
Actual Start: 03/10/2021 **Actual Finish:** 03/10/2021
Project Name:

<u>DATE</u>	<u>COMMENTS</u>
6/12/2020 10:51:22AM	@CDOSIER homeowner Joy Jones called regarding inspectton and asking ifi you can call her att (209) 603-1220
3/10/2021 9:26:00AM	Tree done 22" dbh sttump att locatton
4/8/2021 8:31:11AM	ArcMap updatedd.

Location Information

WO Address: 5340 PASSERO WY
Location: Front

Instructions:

Remove tree.

Map Image Unavailable.jpeg

Completed By: CAMPOS, JOEL A

Date: 03/11/2021

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 3/11/2021 10:15:12AM
Opened By: THOMASON, JUSTIN W
Closed By: THOMASON, JUSTIN W
Actual Start:
Project Name: Stump Removal List

Date: 03/11/2021
Supervisor: WONG, JAMES K
Submit to Date: 03/11/2021
Date: 09/06/2022
Projected Finish: 03/13/2021
Actual Finish: 09/06/2022

<u>DATE</u>	<u>COMMENTS</u>
9/6/2022 4:34:32PM	Stump gone
9/7/2022 9:48:53AM	ArcMap updated.

Location Information

WO Address: 5340 PASSERO WY
Location: Front

Instructions:

Remove 22 DBH Stump.

Map Image Unavailable.jpeg

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB	Date: 03/07/2016
Requested By: FUSON, BOB	Supervisor: FUSON, BOB
Projected Start: 3/7/2016 5:24:30AM	Submit to Date: 03/07/2016
Opened By: FUSON, BOB	Date: 03/10/2016
Closed By: FUSON, BOB	Projected Finish: 03/12/2016
Actual Start:	Actual Finish: 03/10/2016
Project Name:	

<u>DATE</u>	<u>COMMENTS</u>
1/1/1970 12:00:00AM	From Requestt13010: Code: TR006 Descriptton: Permitt Dettails Comments By HEDRICK, BARBARA: 3/3/2016 6:23:29 AM Tree's rootts are impacttng sidewalks and neighbors drivewayItt was plantted ttoo close tto tthe sidewalk. Rec's removal permitt Joy Jones - 209-632-4443 By FUSON, BOB: 3/9/2016 10:24:47 AM Ok tto remove and replace ttree Privett on map needs tto be removed itt is nott a ttræor is itt a citty ttree By HEDRICK, BARBARA: 3/10/2016 7:11:30 AM Emailed permitt and ttree docs tto P@nailed original permitt on 3/16/16. Copy tto file

Location Information

WO Address: 5340 PASSERO WY
Location: 5340 PASSERO WY

Instructions:

Barbie please send the approved tree removal permit and other documentation to the requester.

Completed By: HEDRICK, BARBARA

Date: 03/10/2016

Work Order 30898
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Map Image Unavailable.jpeg

Work Order 31446
Re-Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB	Date: 03/10/2016
Requested By: FUSON, BOB	Supervisor: FUSON, BOB
Projected Start: 5/16/2016 1:53:07PM	Submit to Date: 03/10/2016
Opened By: FUSON, BOB	Date: 06/07/2018
Closed By: FUSON, BOB	Projected Finish: 05/21/2016
Actual Start:	Actual Finish: 06/07/2018
Project Name:	

<u>DATE</u>	<u>COMMENTS</u>
1/1/1970 12:00:00AM	By FUSON, BOB: 3/10/2016 1:53:25 PM
6/7/2018 11:19:06AM	Inspecton fior proper completton ofi ttree removal permitt
6/7/2018 11:19:42AM	Tree 2352 is a glossy-privett which is nott a city tree and is also now 10" sttump
6/7/2018 2:02:09PM	Tree 2636 is sttll here.
	Map/inventtory needs tto be updatedd tto show ttree 2351 as a non-city tree.
	ArcMap updatedd.

Completed By: FUSON, BOB

Date: 06/07/2018

Work Order 31446
Re-Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: FUSON, BOB

Location Information

WO Address: 5340 PASSERO WY

Location: 5340 PASSERO WY

Instructions:

Map Image Unavailable.jpeg

Work Order 61540
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB
Requested By: FUSON, BOB
Projected Start: 2/6/2017 9:50:07AM
Opened By: FUSON, BOB
Closed By: FUSON, BOB
Actual Start:
Project Name:

Date: 02/06/2017
Supervisor: FUSON, BOB
Submit to Date: 02/06/2017
Date: 02/06/2017
Projected Finish: 02/11/2017
Actual Finish: 02/06/2017

Completed By: FUSON, BOB

Date: 02/06/2017

Priority:

5

Category: TREES

Submit To: FUSON, BOB

DATE

1/1/1970 12:00:00AM

COMMENTS

From Request28780:

Code: TR008

Descriptton: Misc Tree issue

Dettails

Comments By FUSON, BOB: 2/6/2017 9:49:55 AM

Trees att curb need maintenanceCaller is firm tthe property managementt company

By FUSON, BOB: 2/6/2017 9:51:46 AM

- Called customer and lefi message Unable tto locatte address
- Customer called and straightttened outt misunderstanding on address
- Lett customer know tthat tthe city is currenttly unable tto trim trees the property owner can do so ifi tthey desireHe will relay infio tto property owner

Location Information

WO Address: 5356 PASSERO WY

Location: 5356 PASSERO WY

Instructions:

Map Image Unavailable.jpeg

Completed By: FUSON, BOB

Date: 02/06/2017

Work Order 11392
Concrete - Curb & Gutter

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: ESTRADA, DOMINIC

Initiated By: JOHNSON, ROBERT L
Requested By: MARCELO, EVEN
Projected Start: 6/11/2015 1:52:15PM
Opened By: GALLAGHER, SEAN
Closed By: GALLAGHER, SEAN
Actual Start:
Project Name:

Date: 06/11/2015
Supervisor: GALLAGHER, SEAN
Submit to Date: 07/08/2015
Date: 07/08/2015
Projected Finish:
Actual Finish: 07/29/2015

<u>DATE</u>	<u>COMMENTS</u>
1/1/1970 12:00:00AM	By JOHNSON, ROBERT L: 6/11/2015 1:52:15 PM i marked multtple locattons thatt need tto be patched bttwn Mosaic Way and GriffierPt Venettan dr. tthanks bob
	By ESTRADA, DOMINIC: 7/29/2015 11:47:53 AM 5 displacemntts repaired

Location Information

WO Address: VENETIAN DR & MOSAIC WY

Location: 2 different areas on Venetian Dr between Mosaic Way & Griffen Pt. both areas are lifted approx 2-3 inches due to city trees

Instructions:

Map Image Unavailable.jpeg

Completed By: ESTRADA, DOMINIC

Date: 07/30/2015

Priority:

3

Category: SW1

Submit To: ESTRADA, DOMINIC



Completed By: ESTRADA, DOMINIC

Date: 07/30/2015

Priority:

3

Category: SW1

Submit To: ESTRADA, DOMINIC



Completed By: ESTRADA, DOMINIC

Date: 07/30/2015

Priority:

3

Category: SW1

Submit To: ESTRADA, DOMINIC



Completed By: ESTRADA, DOMINIC

Date: 07/30/2015

Work Order 11392
Concrete - Curb & Gutter

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: ESTRADA, DOMINIC



Work Order 129520
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: HORTON, ALONZO

Initiated By: FUSON, BOB
Requested By: FUSON, BOB
Projected Start: 1/16/2019 4:23:03PM
Opened By: FUSON, BOB
Closed By: FUSON, BOB
Actual Start:
Project Name:

Date: 01/16/2019
Supervisor: MACHADO, VICTOR
Submit to Date: 01/30/2019
Date: 01/30/2019
Projected Finish: 01/21/2019
Actual Finish: 02/20/2019

Completed By: FUSON, BOB

Date: 02/20/2019

Priority: 5

Category: TREES

Submit To: HORTON, ALONZO

<u>DATE</u>	<u>COMMENTS</u>
1/16/2019 4:23:03PM	From Request60036: Code: TR21 Descriptton: Inspectton Request(Citizen) Dettails Please inspectt tree
1/16/2019 4:23:25PM	Comments Caller requesttng inspectton is neighbor offi property at 1843 Venettan Dr. Inspectt affier sttorm eventt.
1/16/2019 4:51:11PM	Small branch hanging- priority low. Otther tthan thhatt, tree looks tto be ok.
1/30/2019 11:17:00AM	Small-ttomedium limb in ttree on house side offi ttrees will need buckett ttruck or long pole ttto knock itt down.
2/20/2019 1:52:19PM	Limbs picked up.

Location Information

WO Address: 1835 VENETIAN DR
Location: Front

Instructions:

Map Image Unavailable.jpeg

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB	Date: 09/08/2015
Requested By: FUSON, BOB	Supervisor: FUSON, BOB
Projected Start: 9/8/2015 5:02:57AM	Submit to Date: 09/08/2015
Opened By: FUSON, BOB	Date: 07/31/2019
Closed By: FUSON, BOB	Projected Finish: 09/13/2015
Actual Start:	Actual Finish: 09/09/2015
Project Name:	

<u>DATE</u>	<u>COMMENTS</u>
1/1/1970 12:00:00AM	From Requestt7022: Code: TR008 Descriptton: Misc Tree issue Dettails Commentts By DRUM, CAROL: 9/3/2015 3:16:12 PM ROT AT BASE OF TREE. BRADLEY, BOARD OF VENETIANS, 209-479-2086. By FUSON, BOB: 9/9/2015 9:15:37 AM 16" dbh American sweett gum ttree rotted att base aboutt halffi way tthrough tthe trunk like itt was previously sttruck by a vehicle

Location Information

WO Address: 1934 VENETIAN DR
Location: 1934 VENETIAN DR

Instructions:

Completed By: _____

Date: 09/09/2015

Work Order 16598
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Map Image Unavailable.jpeg

Work Order 185336
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: DOSIERSR, CHRIS A

Initiated By: DOSIERSR, CHRIS A
Requested By: DOSIERSR, CHRIS A
Projected Start: 8/17/2020 9:21:40AM
Opened By: DOSIERSR, CHRIS A
Closed By: DOSIERSR, CHRIS A
Actual Start: 08/17/2020
Project Name:

Date: 08/17/2020
Supervisor: DOSIERSR, CHRIS A
Submit to Date: 08/17/2020
Date: 08/17/2020
Projected Finish: 08/22/2020
Actual Finish: 08/17/2020

Completed By: DOSIERSR, CHRIS A

Date: 08/17/2020

Work Order 185336
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: DOSIERSR, CHRIS A

DATE

8/17/2020 9:21:40AM

COMMENTS

From Request84932:

Code: TR21

Description: Inspecton Request(Citizen)

Details

Comments requestt inspecton- tree limbs offien ffiall and homeowner tthinks itt is dying

8/17/2020 10:23:19AM

Tree is in sattsffiactory conditton att tthis ttme.

Location Information

WO Address: 1913 VENETIAN DR

Location: Front

Instructions:

Map Image Unavailable.jpeg

Work Order 217841
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Completed By: THOMASON, JUSTIN W

Date: 08/09/2021

Work Order 217841
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 8/9/2021 5:58:02AM
Opened By: THOMASON, JUSTIN W
Closed By: THOMASON, JUSTIN W
Actual Start:
Project Name:

Date: 08/09/2021
Supervisor: WONG, JAMES K
Submit to Date: 08/09/2021
Date: 08/09/2021
Projected Finish: 08/14/2021
Actual Finish: 08/09/2021

DATE

COMMENTS

8/9/2021 5:58:02AM

From Request#99951:
Code: TR001
Description: Broken/Hanging
Details AskStockton Request#5824496 - Dead tree in sidewalk on Venettan behind Griffin Point property. This is a city tree with no home owner responsible

Attachments

a8645e05-c160-458ffi-881ffi-c5aa5634a1cb301887699166425883.jpg:
<http://user.govoutreach.com/sttocktto/attachmenttphp?request=5824496&access=3636633435323232&aid=2484708d02129c8-1d57-4848-9258-ffi@0364490e21757270433894914362.jpg>:
<http://user.govoutreach.com/sttocktto/attachmenttphp?request=5824496&access=3636633435323232&aid=2484709>

Comments

8/9/2021 10:07:10AM

9 DBH Sweetgum. Dead. Marking for removal.

Location Information

WO Address: 2098 VENETIAN DR
Location: Front

Instructions:

Completed By: THOMASON, JUSTIN W

Date: 08/09/2021

Work Order 217841
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Map Image Unavailable.jpeg

Work Order 217931
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: CAMPOS, JOEL A

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 8/9/2021 10:08:18AM
Opened By: CAMPOS, JOEL A
Closed By: THOMASON, JUSTIN W
Actual Start: 11/29/2021
Project Name: Tree Removal List

Date: 08/09/2021
Supervisor: WONG, JAMES K
Submit to Date: 08/09/2021
Date: 12/02/2021
Projected Finish: 08/11/2023
Actual Finish: 11/29/2021

<u>DATE</u>	<u>COMMENTS</u>
12/2/2021 2:59:57PM	Removed tree leffi 11" dbh sttump
12/10/2021 6:45:11AM	ArcMap updated.

Completed By: CAMPOS, JOEL A

Date: 12/10/2021

Work Order 217931
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: CAMPOS, JOEL A

Location Information

WO Address: 2098 VENETIAN DR

Location: Front

Instructions:

Remove 9 DBH Sweetgum.

Map Image Unavailable.jpeg

Work Order 229174
Stump Removal

Cityworks

Status : PENDING

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 12/10/2021 6:44:37AM
Opened By: THOMASON, JUSTIN W
Closed By:
Actual Start:
Project Name: WE22052 Citywide Tree Maintenance Project

Date: 12/10/2021
Supervisor: WONG, JAMES K
Submit to Date: 12/10/2021
Date: 09/06/2022
Projected Finish: 12/12/2021
Actual Finish:

Completed By: _____

Date: _____

Work Order 229174
Stump Removal

Cityworks

Status : PENDING

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

DATE

9/6/2022 4:36:36PM

COMMENTS

Stump remains

Location Information

WO Address: 2098 VENETIAN DR

Location: Front

Instructions:

Remove 11 DBH Stump

Map Image Unavailable.jpeg

Work Order 36098
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: JOHNSON, ROBERT L

Completed By: JOHNSON, ROBERT L

Date: 05/06/2016

Priority:

5

Category: TREES

Submit To: JOHNSON, ROBERT L

Initiated By: FUSON, BOB	Date: 05/03/2016
Requested By: FUSON, BOB	Supervisor: FUSON, BOB
Projected Start: 5/3/2016 9:40:47AM	Submit to Date: 05/03/2016
Opened By: JOHNSON, ROBERT L	Date: 05/06/2016
Closed By: JOHNSON, ROBERT L	Projected Finish: 05/08/2016
Actual Start:	Actual Finish: 05/06/2016
Project Name: PW9969 2015 Sidewalk Project	

<u>DATE</u>	<u>COMMENTS</u>
1/1/1970 12:00:00AM	From Requestt15467: Code: TR20 Descriptton: Inspectton Request(Sidewalks) Dettails I would like tto remove ttwo liquid ambers DBH4.2" and 14.5". Thanks Bob J. Commentts By FUSON, BOB: 5/3/2016 9:51:33 AM Recommend removing both ttrees as partt offi sidewalk repair project

Location Information

WO Address: 2022 VENETIAN DR
Location: East side of intersection of Venetian and Loggia way.

Instructions:

Completed By: JOHNSON, ROBERT L

Date: 05/06/2016

Priority:

5

Category: TREES

Submit To: JOHNSON, ROBERT L

Map Image Unavailable.jpeg

Work Order 119235
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB	Date: 09/20/2018
Requested By: FUSON, BOB	Supervisor: MACHADO, VICTOR
Projected Start: 9/20/2018 6:42:44AM	Submit to Date: 09/20/2018
Opened By: FUSON, BOB	Date: 07/31/2019
Closed By: FUSON, BOB	Projected Finish: 09/25/2018
Actual Start:	Actual Finish: 11/03/2018
Project Name: PW1815 Sidewalk, Curb, and Gutter Repair Program FY 2018-19 SB1	

<u>DATE</u>	<u>COMMENTS</u>
9/20/2018 6:42:45AM	From Requesti54808: Code: TR20 Description: Inspection Requesti(Sidewalks) Details Inspecti 3tires Commentis
11/3/2018 10:18:28AM	Recommend removing tihree tires as parti offi sidewalk repair/replacementi projecti PW1815.

Location Information

WO Address: 2314 VENETIAN DR
Location: VENETIAN DR & MOSAIC WY

Instructions:

Map Image Unavailable.jpeg

Completed By: FUSON, BOB

Date: 11/03/2018

Work Order 119235
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Work Order 147991
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB
Requested By: FUSON, BOB
Projected Start: 8/6/2019 11:01:13AM
Opened By: FUSON, BOB
Closed By: FUSON, BOB
Actual Start:
Project Name:

Date: 08/06/2019
Supervisor: MACHADO, VICTOR
Submit to Date: 08/06/2019
Date: 08/06/2019
Projected Finish: 08/11/2019
Actual Finish: 08/06/2019

DATE
8/6/2019 11:01:13AM

COMMENTS
From Requesti68807:
Code: TR21
Description: Inspection Requesti(Citizen)
Details Please inspecti tiwo Sweetigum tires her
Caller said tihey are dying and would like tio
know why. She would like tio replanti tires here
Commentis
8/6/2019 11:31:29AM Tree 2849 13" dbh dead sweetigum tireeLikely cause offi dying is evidence offi hiti by vehicle near
base offi tree
Small 3" dbh red maple likely died due tio lack offi care since being planted
8/6/2019 11:44:12AM Customer will need tio discuss planting new tires with Community Developmenti.

Location Information

WO Address: 2301 VENETIAN DR
Location: n/s/o Venetian @ Academy Ct

Instructions:

Completed By: FUSON, BOB

Date: 08/06/2019

Work Order 147991
Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Map Image Unavailable.jpeg

Work Order 147996
Tree Removal Contractor (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: FUSON, BOB	Date: 08/06/2019
Requested By: FUSON, BOB	Supervisor: WONG, JAMES K
Projected Start: 10/7/2019 12:00:00PM	Submit to Date: 11/19/2020
Opened By: THOMASON, JUSTIN W	Date: 08/23/2021
Closed By: THOMASON, JUSTIN W	Projected Finish: 11/05/2021
Actual Start:	Actual Finish: 05/25/2021
Project Name: PW2124 Tree/Stump Removal	

<u>DATE</u>	<u>COMMENTS</u>
8/6/2019 11:32:19AM	13" dbh dead sweetgum tree. Marked for removal.
11/17/2020 3:19:33PM	Per sr:89209 from Victor Machado Change street tree related WO's to show James as the Supervisor."
1/26/2021 11:37:17AM	Projected Finish Date updated to reflect contract completion date off 11/5/2021.
8/19/2021 8:54:42AM	Tree and stump was removed as part off projecti WP21024.
9/16/2021 11:12:01AM	ArcMap updated.

Completed By: PHAN, THINH

Date: 08/23/2021

Work Order 147996
Tree Removal Contractor (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: THOMASON, JUSTIN W

Location Information

WO Address: 2301 VENETIAN DR

Location: n/s/o Venetian @ Academy Ct

Instructions:

Map Image Unavailable.jpeg

Work Order 147997
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

Initiated By: FUSON, BOB
Requested By: FUSON, BOB
Projected Start: 8/6/2019 11:38:57AM
Opened By: FUSON, BOB
Closed By: FUSON, BOB
Actual Start:
Project Name: Tree Removal List

Date: 08/06/2019
Supervisor: MACHADO, VICTOR
Submit to Date: 08/06/2019
Date: 08/06/2019
Projected Finish: 08/08/2019
Actual Finish: 08/06/2019

Completed By: FUSON, BOB

Date: 08/06/2019

Work Order 147997
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: FUSON, BOB

DATE

8/6/2019 11:38:57AM

10/7/2019 7:50:08AM

COMMENTS

3" dbh dead red maple. Tree removed. 4" stump remaining.

ArcMap updated.

Location Information

WO Address: 2301 VENETIAN DR

Location: Front

Instructions:

Map Image Unavailable.jpeg

Work Order 147998
Stump Removal

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: THOMASON, JUSTIN W

Completed By: PHAN, THINH

Date: 08/25/2021

Work Order 147998
Stump Removal

Cityworks

Status : CLOSED

Priority:

5

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: FUSON, BOB	Date: 08/06/2019
Requested By: FUSON, BOB	Supervisor: WONG, JAMES K
Projected Start: 10/7/2019 11:40:00AM	Submit to Date: 11/18/2020
Opened By: FUSON, BOB	Date: 11/18/2020
Closed By: THOMASON, JUSTIN W	Projected Finish: 11/05/2021
Actual Start:	Actual Finish: 06/09/2021
Project Name: PW2124 Tree/Stump Removal	

<u>DATE</u>	<u>COMMENTS</u>
8/6/2019 11:40:37AM	4" stump remaining. Projected removal FY 19-21.
11/17/2020 3:19:33PM	Per sr:89209 ffrom Victior Machad&Change stireeti tiree relatied WO's tio show James as tihe Supervisor."
1/25/2021 2:58:03PM	Projected Finish Datie updatied tio reffiecti contracti completion datie offi 11/5/2021.
8/19/2021 3:36:06PM	The stiump was removed as parti offi Projecti WP21024.
9/17/2021 2:31:07PM	ArcMap updatied.

Location Information

WO Address: 2301 VENETIAN DR
Location: Front

Instructions:

Map Image Unavailable.jpeg

Completed By: PHAN, THINH

Date: 08/25/2021

Priority:

3

Category: TRAFFIC DEVICES

Submit To: FOX, BRIAN

Initiated By: FOX, BRIAN	Date: 05/06/2020
Requested By:	Supervisor: COONS, WILLIAM
Projected Start: 5/6/2020 2:57:27PM	Submit to Date: 05/06/2020
Opened By: FOX, BRIAN	Date: 05/07/2020
Closed By: COONS, WILLIAM	Projected Finish: 05/06/2020
Actual Start:	Actual Finish: 05/12/2020
Project Name:	

<u>DATE</u>	<u>COMMENTS</u>
5/11/2020 3:31:31PM	On 5-11-2020 mr Michael A Gilletti & mr Bryanti Bowen Spent 7 hours working on this work order which included <ol style="list-style-type: none"> 1. Survey area for unpainted median tips 2. Locate several unpainted & / or unmaintained medians 3. Set up traffic control per application 4. Prepare median tips for repairs 5. Scrape / wire brush / de-weed / when necessary 6. Blow areas clean in preparation 7. Re-paint or new paint application on approximately 4 areas 8. Lunchtime allocation 9. Bathroom breaks 10. Remove traffic control 11. Required computer updates
5/12/2020 1:04:26PM	On 5-12-2020 mr Michael A Gilletti II & mr Bryanti Bowen spent 5.25 hours completing this work order which included <ol style="list-style-type: none"> 1. Locate several locations in need of repair/maintenance 2. Set up traffic control per application 3. Prepare areas for repair/new construction 4. Trim bushes / weeds / scrape / sweep / blow / clean areas to be repaired 5. Repair approximately 7 areas of need according to this work order 6. Bathroom break 7. Remove traffic control 8. Lunchtime allocation 9. Required computer updates

Location Information

WO Address: E MARCH LN & HOLMAN RD
Location: all of march ln

Instructions:

paint all yellow in center

Completed By: GILLET, MIKE

Date: 05/13/2020

Work Order 170801
Paint - Curb

Cityworks

Status : CLOSED

Priority:

3

Category: TRAFFIC DEVICES

Submit To: FOX, BRIAN

Map Image Unavailable.jpeg

Work Order 188948
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 9/30/2020 9:01:38AM
Opened By: THOMASON, JUSTIN W
Closed By: THOMASON, JUSTIN W
Actual Start:
Project Name:

Date: 09/30/2020
Supervisor: WONG, JAMES K
Submit to Date: 09/30/2020
Date: 09/30/2020
Projected Finish: 10/05/2020
Actual Finish: 09/30/2020

DATE

COMMENTS

9/30/2020 8:52:30AM

(Copied from Service Request 187182): "tree is starting to come out of the ground and a lump is forming on lawn next to fence

9/30/2020 10:30:52AM

18.5 DBH Sweetgum tree Tree is in satisfactory condition Surface roots present Driveway appears to be damaged by trees root system Sidewalk has been marked out and ramped Will leave door hangar.

9/30/2020 10:31:08AM

Reffer to Community Development iffi Citizen calls in.

Completed By: THOMASON, JUSTIN W

Date: 09/30/2020

Work Order 188948
Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Location Information

WO Address: 2323 VENETIAN DR

Location: Front

Instructions:

Map Image Unavailable.jpeg

Work Order 200067
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

1

Category: TREES

Submit To: CAMPOS, JOEL A

Initiated By: THOMASON, JUSTIN W
Requested By: THOMASON, JUSTIN W
Projected Start: 2/2/2021 8:59:45AM
Opened By: CAMPOS, JOEL A
Closed By: THOMASON, JUSTIN W
Actual Start: 02/05/2021
Project Name:

Date: 02/02/2021
Supervisor: THOMASON, JUSTIN W
Submit to Date: 02/02/2021
Date: 02/09/2021
Projected Finish: 02/04/2021
Actual Finish: 02/05/2021

Completed By: CAMPOS, JOEL A

Date: 02/17/2021

Work Order 200067
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

1

Category: TREES

Submit To: CAMPOS, JOEL A

DATE

COMMENTS

2/2/2021 8:59:45AM

From Request91715:
Code: TR005
Description: Tree down
Details Tree down. Moved outi offi roadway tio side offi stireeti
Commentis

2/9/2021 1:39:42PM

Cleared uprooted tiree blocking sidewalk no stump

2/17/2021 6:35:00AM

no stump.

2/17/2021 7:15:59AM

ArcMap updatied.

Location Information

WO Address: 2301 VENETIAN DR

Location: In gutter

Instructions:

Tree is down. Storm 1/27/2021. Remove. Stump uprooted.

Map Image Unavailable.jpeg

Work Order 44766
Stump Removal

Cityworks

Status : CLOSED

Completed By: PHAN, THINH

Date: 09/07/2021

Work Order 44766
Stump Removal

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Initiated By: FUSON, BOB	Date: 08/09/2016
Requested By: FUSON, BOB	Supervisor: THOMASON, JUSTIN W
Projected Start: 8/9/2016 8:03:42AM	Submit to Date: 11/19/2020
Opened By: FUSON, BOB	Date: 11/19/2020
Closed By: THOMASON, JUSTIN W	Projected Finish: 11/05/2021
Actual Start:	Actual Finish: 06/09/2021
Project Name: PW2124 Tree/Stump Removal	

<u>DATE</u>	<u>COMMENTS</u>
1/1/1970 12:00:00AM	By FUSON, BOB: 8/9/2016 8:03:42 AM 12" dbh stump remaining
10/10/2018 9:19:41AM	@TPENGILL tiree 2123 tiree is still here. Location 2406 tiree is gone with 12" stiump remaining.
10/22/2018 9:41:05AM	Correctied asseti.
11/1/2018 6:38:28AM	ArcMap updatied.
1/26/2021 9:12:28AM	Projectied Finishe Datie updatied tio reffecti contracti completion datie offi 11/5/2021.
8/19/2021 3:36:39PM	The stiump was removed as parti offi Projecti WP21024.
9/20/2021 6:57:54AM	ArcMap updatied.

Location Information

WO Address: 2301 VENETIAN DR
Location: Front

Instructions:

Completed By: PHAN, THINH

Date: 09/07/2021

Priority:

3

Category: TREES

Submit To: THOMASON, JUSTIN W

Map Image Unavailable.jpeg

Work Order 10860

Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L

Initiated By: MARCELO, EVEN
Requested By: MARCELO, EVEN
Projected Start: 6/1/2015 2:22:21PM
Opened By: JOHNSON, ROBERT L
Closed By: MARCELO, EVEN
Actual Start:
Project Name:

Date: 06/01/2015
Supervisor: MARCELO, EVEN
Submit to Date: 06/01/2015
Date: 06/03/2015
Projected Finish:
Actual Finish: 06/03/2015

COMMENTS

1/1/1970 12:00:00AM

From Request 4386:

10,511.00

Code: SW01

Description: Curb, Gutter, Sidewalk Issue

Details: Her husband is in a wheelchair and it's a trip hazard. She would like a returned call after inspection.

Comments:

By JOHNSON, ROBERT L: 6/3/2015 2:28:29 PM

There is no public sidewalk leading to the walkway. It is private property not a City issue. Please see pic.

Location Information

WO Address: 1834 VENETIAN DR

Location: Sidewalk leading to walkway to gate is uplifted and cracked. No city trees around.

Instructions:

Assets:

ID	Type
1834 VENETIAN DR	MASTERADDRESS_POINTS



Completed By: JOHNSON, ROBERT L

Date: 06/04/2015

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L



Completed By: JOHNSON, ROBERT L

Date: 06/04/2015

Work Order 11133

Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L

Initiated By: MARCELO, EVEN
Requested By:
Projected Start: 6/8/2015 8:02:28AM
Opened By: JOHNSON, ROBERT L
Closed By: MARCELO, EVEN
Actual Start:
Project Name: Future Sidewalk Repairs

Date: 06/08/2015
Supervisor:
Submit to Date: 06/08/2015
Date: 06/11/2015
Projected Finish:
Actual Finish: 06/11/2015

COMMENTS

1/1/1970 12:00:00AM

From Request 4508:

10,784.00

Code: SW01

Description: Curb, Gutter, Sidewalk Issue

Details:

Comments:

By JOHNSON, ROBERT L: 6/11/2015 1:45:36 PM

i marked 8 - 10 locations on venetian dr between masaic way and griffen point that need to be patched . thanks

Location Information


WO Address: VENETIAN DR & MOSAIC WY

Location: 2 different areas on Venetian Dr between Mosaic Way & Griffen Pt. both areas are lifted approx 2-3 inches due to city trees

Instructions:

Assets:

ID	Type
2314 VENETIAN DR	MASTERADDRESS_POINTS



Completed By: JOHNSON, ROBERT L

Date: 06/15/2015

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L



Completed By: JOHNSON, ROBERT L

Date: 06/15/2015

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L



Completed By: JOHNSON, ROBERT L

Date: 06/15/2015

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L



Completed By: JOHNSON, ROBERT L

Date: 06/15/2015

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L



Completed By: JOHNSON, ROBERT L

Date: 06/15/2015

Work Order 16776
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:

3

Category: TREES

Submit To: WALLACE, JAMES M

Initiated By: FUSON, BOB	Date: 09/09/2015
Requested By: FUSON, BOB	Supervisor: FUSON, BOB
Projected Start: 9/14/2015 9:17:36AM	Submit to Date: 09/09/2015
Opened By: WALLACE, JAMES M	Date: 09/10/2015
Closed By: FUSON, BOB	Projected Finish: 09/16/2015
Actual Start: 09/03/2015	Actual Finish: 09/10/2015

Project Name:

COMMENTS

1/1/1970 12:00:00AM

By FUSON, BOB: 9/9/2015 9:18:56 AM 16,121.00
16" dbh American sweet gum tree rotted half way through bottom four feet of trunk . Tree Crew remove tree.

By FUSON, BOB: 9/9/2015 9:20:34 AM
Tree marked for removal.

By WALLACE, JAMES M: 9/10/2015 10:55:27 AM
20" stump remaining

By PENGILLY, TRACY: 10/22/2015 8:29:56 AM
ArcMap updated.

Location Information

WO Address: 1934 VENETIAN DR
Location: 1934 VENETIAN DR

Instructions:

Completed By: WALLACE, JAMES M

Date: 09/10/2015

Work Order 16776
Tree Removal COS (Non-Emergency)

Cityworks

Status : CLOSED

Priority:


3

Category: TREES

Submit To: WALLACE, JAMES M

Assets:

ID	Type
AR5 20130102144925	TREES



Completed By: WALLACE, JAMES M

Date: 09/10/2015

Work Order 27611
Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: SW1

Submit To: JOHNSON, ROBERT L

Initiated By: JOHNSON, ROBERT L
Requested By: JOHNSON, ROBERT L
Projected Start: 1/20/2016 8:38:08AM
Opened By: JOHNSON, ROBERT L
Closed By: JOHNSON, ROBERT L
Actual Start:
Project Name:

Date: 01/20/2016
Supervisor: ALMASSY, JODI
Submit to Date: 01/20/2016
Date: 01/29/2016
Projected Finish:
Actual Finish: 01/29/2016

COMMENTS

1/1/1970 12:00:00AM

From Request 11250:

26,018.00

Code: SW01

Description: Curb, Gutter, Sidewalk Issue

Details:

Comments:

Location Information

WO Address: GRIFFIN PT & VENETIAN DR

Location: Approx. 100' in on Griffin Pt there is a 24" x 24" sink hole in the sidewalk.

Instructions:

I saw a small pothole that was already filled with cutback. Thanks. Bob

Assets:

ID	Type
1577 GRIFFIN PT	MASTERADDRESS_POINTS

Map Image Unavailable.jpeg

Completed By: JOHNSON, ROBERT L

Date: 01/29/2016

Work Order 31299
Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: SW1

Submit To: JOHNSON, ROBERT L

Initiated By: JOHNSON, ROBERT L
Requested By: JOHNSON, ROBERT L
Projected Start: 3/9/2016 11:34:48AM
Opened By: JOHNSON, ROBERT L
Closed By: ALHINDI, OMAR
Actual Start:
Project Name:

Date: 03/09/2016
Supervisor: ALMASSY, JODI
Submit to Date: 03/09/2016
Date: 03/22/2016
Projected Finish:
Actual Finish: 03/22/2016

COMMENTS

1/1/1970 12:00:00AM

From Request 13191:

29,621.00

Code: SW01

Description: Curb, Gutter, Sidewalk Issue

Details: Citizen would like a call back regarding the sidewalk.

Comments:

By JOHNSON, ROBERT L: 3/22/2016 11:23:31 AM

Inspected sidewalk and it appears to be fine, please see pictures.

Location Information

WO Address: 1834 VENETIAN DR

Location: Sidewalk raised due to City tree and has holes in it.

Instructions:

Assets:

<u>ID</u>	<u>Type</u>
1834 VENETIAN DR	MASTERADDRESS_POINTS

Map Image Unavailable.jpeg

Completed By: JOHNSON, ROBERT L

Date: 04/18/2017

Work Order 31299
Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

5

Category: SW1

Submit To: JOHNSON, ROBERT L

Completed By: JOHNSON, ROBERT L

Date: 04/18/2017

Work Order 84869
Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: PHAN, THINH

Initiated By: PHAN, THINH
Requested By: JOHNSON, ROBERT L
Projected Start: 9/25/2017 9:30:26AM
Opened By: PHAN, THINH
Closed By: TEJADA, ANGEL
Actual Start:
Project Name: Future Sidewalk Repairs

Date: 09/25/2017
Supervisor: ALHINDI, OMAR
Submit to Date: 09/25/2017
Date: 09/23/2021
Projected Finish: 09/25/2017
Actual Finish: 09/25/2017

COMMENTS

9/25/2017 9:30:27AM PHAN, THINH

81,757.00

From Request 39870:
Code: SW08
Description: Claim
Details: Sidewalk is Uplifted 1-2 inches, due to City Tree

****Note:** Please take photos of sidewalk before work is completed** Requested by Risk
Comments:

9/25/2017 12:24:24PM PHAN, THINH

The uplifted sidewalk was damaged by a City control tree. I marked approx. 10 sidewalk locations for temporary AC patching on Venetian Dr from Lido to Mosaic.

81,757.00

Location Information

WO Address: 2436 VENETIAN DR
Location: Across from 2335 Lido Ct on Venetian Dr

Instructions:

Completed By: PHAN, THINH

Date: 04/04/2018

Priority:

3

Category: SW1

Submit To: PHAN, THINH

Assets:

<u>ID</u>	<u>Type</u>
2436 VENETIAN DR	MASTERADDRESS_POINTS

Map Image Unavailable.jpeg

Completed By: PHAN, THINH

Date: 04/04/2018

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 04/04/2018

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 04/04/2018

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 04/04/2018

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 04/04/2018

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 04/04/2018

Work Order 98236
Special Reinspection

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L

Initiated By: TEJADA, ANGEL **Date:** 02/08/2018
Requested By: TEJADA, ANGEL **Supervisor:** ALHINDI, OMAR
Projected Start: 2/8/2018 7:09:20AM **Submit to Date:** 09/25/2018
Opened By: JOHNSON, ROBERT L **Date:** 09/27/2018
Closed By: PHAN, THINH **Projected Finish:** 02/08/2018
Actual Start: **Actual Finish:** 09/27/2018
Project Name:

COMMENTS

9/27/2018 8:08:12AM JOHNSON, ROBERT L

The sidewalk at this location has been replaced. The trees were not removed and have dislocated the sidewalk again. 94,987.00
The trees needs to be be removed and the sidewalk replaced. Bob

2/8/2018 7:09:20AM TEJADA, ANGEL

CASS WORK Closed due to Age-Sidewalk Reinspection 94,987.00

-SIDEWALK RAISED CAUSING A TRIP HAZARD. PLEASE CALL REGARDING YOUR FINDINGS.

INSPECTION DATE: 8/18/2005

INSPECTION NOTES: TREES HAVE RAISED AREAS IN THE BANK AREA THAT THEY WOULD LIKE TO FIX BUT TREES WOULD NEED TO COME OUT. REFER TO TREE CREW.

Location Information

WO Address: 1546 ST MARKS PZ

Location: 1556 ST MARKS PZ

Instructions:

Reinspect to see if sidewalk was removed and replaced.

Completed By: JOHNSON, ROBERT L

Date: 10/23/2018

Priority:

3

Category: SW1

Submit To: JOHNSON, ROBERT L

Assets:

<u>ID</u>	<u>Type</u>
1546 ST MARKS PZ	MASTERADDRESS_POINTS

Map Image Unavailable.jpeg

Completed By: JOHNSON, ROBERT L

Date: 10/23/2018

Priority: 5

Category: TREES

Submit To: FUSON, BOB

Assets:

<u>ID</u>	<u>Type</u>
AR5 20130102143812	TREES
AR5 20130102144019	TREES



Completed By: FUSON, BOB

Date: 11/03/2018

Work Order 143664
Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: PHAN, THINH

Initiated By: PHAN, THINH
Requested By: JOHNSON, ROBERT L
Projected Start: 6/19/2019 12:01:48PM
Opened By: PHAN, THINH
Closed By: PHAN, THINH
Actual Start:
Project Name:

Date: 06/19/2019
Supervisor: ALHINDI, OMAR
Submit to Date: 06/19/2019
Date: 03/24/2022
Projected Finish: 06/19/2019
Actual Finish: 07/09/2019

COMMENTS

6/19/2019 12:01:48PM PHAN, THINH

140,306.00

From Request 66222:

Code: SW08

Description: Claim

Details: We received the attached claim. The claimant tripped on the raised sidewalk patch on 01/29/19 and sustained injury. My inspection photos show custom red pavement between the curb and sidewalk, and a sidewalk tree approximately 6' feet from the condition. It appears the sidewalk was uplifted by the tree roots. Checking for any PW records for the trees and sidewalk at the location. Need to verify if the trees belong to the City and if the City or the property owner would be responsible for th

Comments:

7/9/2019 9:46:17AM PHAN, THINH

140,306.00

Per my inspection, the sidewalk was uplifted by City tree roots. There are existing ac patching, but the sidewalk will need additional patching to make it safe.

Location Information

WO Address: 1934 VENETIAN DR

Location: (between Loggia Way & Bellini Way)

Instructions:

Completed By: PHAN, THINH

Date: 08/01/2019

Priority:


3

Category: SW1

Submit To: PHAN, THINH

Assets:

<u>ID</u>	<u>Type</u>
1934 VENETIAN DR	MASTERADDRESS_POINTS



Completed By: PHAN, THINH

Date: 08/01/2019

Work Order 149580
Sidewalk Inspection

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: PHAN, THINH

Initiated By: PHAN, THINH
Requested By: JOHNSON, ROBERT L
Projected Start: 8/21/2019 2:24:02PM
Opened By: PHAN, THINH
Closed By: PHAN, THINH
Actual Start:
Project Name: Future Sidewalk Repairs

Date: 08/21/2019
Supervisor: ALHINDI, OMAR
Submit to Date: 08/21/2019
Date: 03/30/2020
Projected Finish: 08/21/2019
Actual Finish: 08/23/2019

COMMENTS

8/23/2019 2:41:39PM PHAN, THINH

Per my inspection, the sidewalk was uplifted by City tree roots. I marked several sidewalk locations with white paint for temporary sidewalk repair. 146,206.00

8/21/2019 2:24:03PM PHAN, THINH

146,206.00

From Request 68841:
Code: SW01
Description: Curb, Gutter, Sidewalk Issue
Details: AskStockton Request # 4601046 - Sidewalks are dangerous, trees are uprooting entire sidewalk
Comments:

Location Information

WO Address: 2436 VENETIAN DR
Location: 2436 VENETIAN DR

Instructions:

Completed By: PHAN, THINH

Date: 03/30/2020

Priority:


3

Category: SW1

Submit To: PHAN, THINH

Assets:

<u>ID</u>	<u>Type</u>
2436 VENETIAN DR	MASTERADDRESS_POINTS



Completed By: PHAN, THINH

Date: 03/30/2020

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 03/30/2020

Priority:

3

Category: SW1

Submit To: PHAN, THINH



Completed By: PHAN, THINH

Date: 03/30/2020

Work Order 149951 Temporary Sidewalk Repair

Cityworks

Status : CLOSED

Priority:

3

Category: SW1

Submit To: COONS, WILLIAM

Initiated By: PHAN, THINH
Requested By: JOHNSON, ROBERT L
Projected Start: 8/23/2019 2:41:39PM
Opened By: COONS, WILLIAM
Closed By: COONS, WILLIAM
Actual Start:
Project Name: Future Sidewalk Repairs

Date: 08/23/2019
Supervisor: COONS, WILLIAM
Submit to Date: 04/20/2020
Date: 04/21/2020
Projected Finish: 08/23/2019
Actual Finish: 04/20/2020

COMMENTS

8/23/2019 2:41:39PM PHAN, THINH

I marked several sidewalk locations with white paint for temporary sidewalk repair. Thank you

146,575.00

4/20/2020 9:57:43AM SPRAGG, JOHN

Filled 21 large displacements using 8 buckets of trowel pave

146,575.00

Location Information


WO Address: 2436 VENETIAN DR

Location: 2436 VENETIAN DR

Instructions:

Assets:

ID	Type
2436 VENETIAN DR	MASTERADDRESS_POINTS



Completed By: SPRAGG, JOHN

Date: 04/21/2020

Priority:

3

Category: SW1

Submit To: COONS, WILLIAM



Completed By: SPRAGG, JOHN

Date: 04/21/2020

Priority:

3

Category: SW1

Submit To: COONS, WILLIAM



Completed By: SPRAGG, JOHN

Date: 04/21/2020